


SE Bländaren kan ej byggas om mellan 150-153 c/c och 160 c/c med att byta anslutning.
 ENG The mixer cannot be rebuilt between 150 and 160 c/c by switching the connectors.



9000 thermostatic mixer. Produced from 1999.

Article number: 92100000_variant

Uniqe characteristics